to Of F. M. HARDEN, Lt. Col.

WAR DEPARTMENT HEADQUARTERS ARMY AIR FORCES-WASHINGTON

7823

MISSING ALL CHAN ENTORY

	A CONTRACTOR OF THE PROPERTY OF THE PARTY OF		
		Il be commiled in triplicate by each Army	
		dthin 48 hours of the time an aircraft is	OILICIBILY
3	reported missi	FF Station 131 : Command or Air Force 8	th Air Force
- •	Commercial Doubles and Her and	Squadron 603rd Bomb Hv ; Detachment N	ONA
_	Croup System Bond hy	AAF Station 131 Course per atchd	track chart
4.	Trianged Destination to	Course to Petrone Course Per Con	mattens?
WEA	THE TOTAL PROTUCTION OF THE TOTAL STRUCT	na. Germany & Return Type of Mission Ope TY AT TIME OF CRASH OR WHEN LAST REPORTED:	Z B OT OTT
oz –	(6) to seven (7) tenths clos	ud coverage-visibility unrestricted, horiz	ontally 12-1
4.		Timeapprox 0939; and Location Teur IP (S	onder unn sen
	of last known whereabouts		٠. دا
	(b) Specify whether (x) Lest Sighted, () Lest Contacted by Rud	12.0
5	ATROPART WAS LOST OR IS RE	to crash, or () Information not Available LIEVED TO HAVE BEEN LOST, AS A RESULT OF:	(Chack only
J.		(x) Enemy Anti-Aircraft, () Other Circu	
	Follows	(A / Linear state and control of the	
			· · ·
6.	AIRGRAFT: Type, Model and S	eries Bl7G ; A.A.F. Serial Number 42-10	2579
		eriesR-1820-97; A.A.F. Serial Number	
• •	(a) 87-014836 : (b)	SM-0147S7 ; (c) SM-014841 ; (d)	SN-014750
8.	INSTALLED FEAPONS (Furnish	below Make, Type and Serial Number)	
•	VAKE	TYPE SERIAL M	IM. ER
(a)	Frig. Div. Gem. Motors	.50 cal A/C machgum 731306	
(b)	Frig. Div. Gen. Motors	.50 cal A/C mach gum 713038	,
(c)	Frig. Div. Gen. Motors	.50 oal A/C mach gum 152862	.
(a)	Frig. Div. Gem. Motors	.50 cal A/C mach gum 157866	50 PM
(e)	Frig. Div. Gen. Motors	.50 cal A/C mach gum 648945	5
(f)	Frig. Div. Gen. Motors	.50 cal A/C mach gun 647186	; ·
(g) (h)	Frig. Div. Gem. Motors	.50 cal A/C mach gum 77887	•
(T)	Frig. Div. Gen. Motors	.50 cal A/C mach gun 972100	
(4)	General Motors	.50 cal 1/C mech gum 152826	
(1) (1)	General Motors	.50 cal A C mach gum 152905	
	Governor Wo day p	.50 cal A/C mach gum 152901	
(m)	General Motors	.50 cal A/C mach gum 971967	
(n)	•		
(0)	•		
(a)		01	
\q\			S 19
(T)			- (
(1) (m) (n) (o) (p) (r) (t) (t)			
9	THE PERSONS LISTED BELOW WE	RE REPORTED AS: (a) Battle Casualty MU	

CONFIDENTIAL

or (b) Non-Battle Casualty

Jul 23'

COMFIDERTIAL

10.	NUMBER OF PERCORS AS	CARD ATRCRAFT:	urem 9	Passengere		ce it
	CREE POSTERON	N	AME IF FULL	The second second	A.	
· · · · · · · · · · · · · · · · · · ·			st Name Fire	t) BAR		B (C
1.	Pilot	THE RELLEGIO	SUR S	ist it to	CONTRACT	RIL
2 .	Co-Pilet	A TILIAUS.	CLAUDE A	2nd lik	24117	
	Invigator	AA73. 7085	H H	and Lt	0-705292	
4.	Bambardier	M/WOOLLEY, R	BERT A	2nd Lt	0-757762	RTD
5.	ENE TURRET GUENER	Boorma, P	ed	T Sgt	36724862	ን ምን
6.	Radio Sumer	M' foldy, Beg	topic u	7 Sgt	11035576	R+D
7.	Left Waist Gumer	-Ford, Loca		S Sgt	11082576	RTD
8.	Ball Turret Gummer	A Hovey, Ric	mid I	8 Bgt	\$766589.3	RID
9.	Tail Gummer	Marriagton	and the later was a later with the l	8 Sgt	12096816	Rimi
		artines on the case of the significant of the second				<u> </u>
,11.	the same of the sa		·	· 		
12.				~.~~~		
11.	IDENTIFY BELOW THOSE	PERSONS WHO ARE	SELIEVED TO	HAVE LAST KNOW	EDGE OF ATR	CRAFT
	AND CHECK APPROPRIA	TE COLUMN TO IND	ICATE BASIS	FOR SAME: (C)	nack Only On	B)
		•	Cont	acted		87
	Name in Full	5		y Lest		orced
•	(Last Name First)			dio Sighted	<u>Cresh</u> <u>L</u>	endire
	KOVACEV, SPECHAN	. T Szt		<u> </u>		· ·
	MORRIS, STACEY, JR.	S Sgt .3		<u> </u>	-	
3. ,	HUMBERT, JAISS A	3 Set 3	3508433	T.		
	STATEMENTS: (a) Parafrom scene of crass Alectait was undercon ATTACH LERIAL PHOTOG WHERE AIRCRAFT WAS	achutes were used h	Any other r	Persons were peason (Specify	soe a wallding	away
là.	EXECTTIESS DESCRIPTION	ON OF CRASH FO	ROWD TANDTNO	י אמדיה פיונצייה חום	THE CONTRACTOR OF	676
	TAINING TO MISSING	AIRCRAFT:	MATERIAL TRANSPORTER	, OR OTHER CIRC	orstands s	
					•	,
	(Eve Witness	Statements Attaci	(aa)	•	•	•
	()	Post of Total		*	•	
				•	•	
15.	ATTACH A DESCRIPTION SERIAL NUMBER OF OFF	OF THE EXTENT OF ICER IN CHARGE H	SEARCH, IF	ANY, AND GIVE	NAME, RANK A	MD
			_			
			Date of R	eport 31 July	194	
	BECEINED				7	
	Garage	•				
	5.2		Malli	J. Comple	art.	
				nature of Frens		7
	(c) (B) ()6			L CAMPIFELL	- THE OTTICE!	• •
	2		lst Lt,	Air Corps		
		•	Statist	ical Control of	ficer	

WOURT 38 CONFIDENTIAL

398th Lombardment Group Hv Leuna, Germany Eission 28 July 1944

Lead Group "A" 1st CBW Formation after Assembly

F-12 STYERAL DOUGLAS C-3 7746-7 F-10 BESTERVELT Ford 2467-J RICE 7975-2 C-1 C-5 Melson Elwooi 7399-H C-1 2390-X 0-2 C-6 C-2 Searl Rengel Fritog Theeler 7 67-5 2536-C 2592-G 7249-P B-1 Kaufman 2469-0 3-5 Fi sher Sisaman 7977-R 7078-U

High Group "A" lat CHW Formation After Assembly

D-7 Griffen 7874-K

D-5 D-1 Darner Heintzelman 7401-I 7098-Y D-6 D-10 Davis, JH Hornshuh 2565-M 7385-X D-2 D-4 D-3 McCarty **Fairbanks** Farnsworth 7889-B 7509-7190-L 2515-H B-4 D-10 Durtschi Slavin 7825-J C-4 B--3 2607-F Dwye. Engel

Low Group "A" 1st CBW Formation After Assembly

P_0 Allen 2610-Y F-2 P- 4 Hoodson Clark 2543-3 7183-J P-5 F-8 Ryan Turner 7387-H F-6 F-7 7387-R F-7 F-3. Frigom Boebme Dollar Roderick 7094-1 2597-V 2593-C 737 (- X B-6 Lassegard 2570-2 3-5 B .. 7 CONFIDENTIAL Ecwden abrestheid 5083-Y /138-T

Eye Witness Description of Missing Aircraft Bl7G 42-102574, Pilot 1st Lt Wilbur S Dwyer, 0-808046, 605rd Bomb Squadron, 19812 Lomb Group missing from operational mission to Leune, Germany 28 Jul; 1944.

On the 2ath day of July on way to Leunn, Germany I saw Lt Dwyer feather his number three engine after it had been smoking badly. He then propped back, because he could not keep up with the formation. After about ten minutes or falling back he started his engine again, but again it started smoking. This time he dropped way back and knowing he could not beep up with the formation he peeled off to the right. This was the last time I saw him.

STAPSKN KOVACAV, 36292252 S Sgt, 502nd Bomb Sq. Radio Gunner, Bl7G 42-102593

CONFIDENTIAL

By Witness Description of Missing Aircraft Blvg 42-102579, Wilot, 1st It Wilbur S Dayer, 0-006590, 605rd Bomb Squadron, 598th Bomb Group missing from Leuna, Germany mission 28 July 1944.

I was flying as ball turret gummer on Lt Wierney's crew on a raid of Leuna, Germany 28 July 1944 when I saw Lt Dwyer feather a propellor.

I noticed that he had trouble holding his position as number two ship of second element in low squadron, high group, but his engine wasn't smoking. About ten minutes from the target, Lt Dwyer made a turn to the right and was heading for home.

We had fighter support on that day and when Lt Dwyer started back, I saw some fighters, which were flying just above the clouds, head toward his plane. Whether they were our fighters or German I don't know because they were too far away to recognize.

We relie over the target shortly after and I didn't see what happened to Lt Dayer.

STACEY MORRIS, JR., 35832394

Gaces Morris

S/Sgt, 601st Bomb Sq.

Ball Turret Gunner, 3179 43-37509

Eye Fitness Description of Missing Aircraft B17G 42-102574, Pilot, 1st Lt Wilbur S Dwyer, 0-808546, 605rd Bomb Squadron, 348th Bomb Group on Combat Wission to Leuna, Germany 28 July 1944.

I was flying with Lt Durtschi as Tatl Gummer on the raid to Leuna, Germany on 28 July 1944. We were flying lead of second element of low squadron, high group and Lt Dwyer was flying number two position of second element of light squadron high group. On way to target Lt Dwyer had trouble holding his position in formation because of prop wash.

About ten minutes from the target Lt Dwyer feathered his number three engine. His aircraft then dropped out of formation. Shortly after, he started the engine and caught up with our formation but at a lower altitude. It was evident he couldn't keep the engine going as he again feathered it and dropped further back. He then salvoed his bomb load and made a right turn heading toward another group that had hit the target and was on course I observed no smoke or five from the aircraft.

JAMES A HURBERT, 35602499 S/Sgt, 603rd B rb Sq Tail Gunner, B17G 43-37825

- BONFIDENTIAL

Section 1

HEAPQUARTERS EUPOPEAN THEATER OF OPERATIONS P/W and X Detechment Military Intelligence Service

REPORT FOR THE ADJUTANT GENERAL'S OFFICE

Except 20 DY 1/	3gt 11065	576	9 Soptember 1964	_
(Name)	(Rank)	ASN	(Date)	
603 Bomb Squadron	398 Bomb Gro	HZ0	F&R 1855	
	Unit		(IS9(TEA)/6/79/725)	

			,	PRESENT
		1:33	BERS OF CREH	OFFICIAL STATUS
See Off	0.000000	7 **	Walter and D. Tribler	र∗/ज
FILOT CO-PILOT	0-808596 0-699497		Wilms 3 LAYER Claude A WILLIAMS	P/T
NAVIGATOR	0-703292	2nd Lt	Joseph 2012	P/ਬ
BOMBARDIER	0-757762		Robert A WOOLEY	P/H
RADIC OPÉRATOR	11065576		Eugene ZOLDY	ETD .
TOP TURRET GUINER	36724862		Ted BORSKIA	P/T
BALL TURRET GUNNER	,		Leon W FORD	RTD
WAIST GINNER	37665898	S/Sot.	Righard TOUSY	P/4
TAIL GUNNER	NONE 12096638	S/Sgt	Robert R HARPINGTON	P/4
•	220,00000	-4 -6:	the state of the s	, -, -

Date, time and approximate location of plane crosh or landing. 28 July 1944; 1200 hours; vicinity of Maredret.

Nature and extent of damage to plane when source bailed out. Was it on fire, etc? Three engines were throwing out oil continuously.

At approximately what altitude cid source bail out?

900 feet.

Were any of the crew injured or killse before the plane crashed?

No

What members of the crew boiled out? Did their parachutes open? All bailed out and all chutes opened.

Did the plane explode on striking the ground?

Did source see any other members of the craid dead or alive after reaching the ground?
Yes, Syst Leon Ford.

Pid he receive any information from others as to whether any other members of the crew were dead or alive? If so, give details furnished by his informant and whether the other crew members were identified by name or otherwise.

Yes: S/Sgt Leon Ford was with the underground: S/Sgt Hovey was turned over to the Germana because proper medical attention could not be six was its condition?

Plane exploded and blew up four houses.

If the plane crashed in water how far was the plane from land and by what means was source rescured and what life rifts, wreckage, etc., remained on the surface that would have assisted other personnel to keep afloat.

Kot given.

What is source's opinion as to the fate of the other crew members and his reason for his opinion?

Chutes were too small and three men that I know of sprained or broke their ankles. The pilot escaped but no one knew whore he was and the rest were prisoners. S/Sgt Ford and Hovey were identified by name.

ChorET

HEADQUARTERS EUROPEAN THEATER OF OPERATIONS P/W and X Detachment Military Intelligence Service

REPORT FOR THE ADJUTANT GENERAL'S OFFICE

Leon W FORD	S/9-t.	11082376	II September 1944
(Name)	(Rank)	ASN	(Date)
503 Bonb Squa	dron, 398 Bo	Group	B&E 1980
	(Unit		(TS9(TRA)/6/125/846)

		BERS	S OF CREM	PRESENT OFFICIAL STATUS
PILOT CO-PILOT NAVIGATOR MAVIGATOR BUMBARDIER PADIO OPERATOR TOP TURPET GUNNER RALL TURRET GUNNER WALST GUNNER HAIST GUNNER TAIL GUNNER	0-808596 0-699497 0-703292 0-757762 11065576 36724862 11082376 37665898 NONE	lst Lt 2nd Lt 2nd Lt 2nd Lt 7/Sgt 7/Sgt 5/Sgt S/Sgt	Wilbur S DIER Thende A WHALIANS Joseph MUTZ Robert A WOOLST Rogene SOLDI Ted BORSKAL Lion T FORD Richard muyey Robert E HARRINGTON	P/#

Date, time and approximate Lucation of plane crash or landing. 28 July 1944; 1200 hours;

Nature and extent of damage to plane when source bailed out. Was it on fire, etc? Three engines cut; no fire.

At approximately what altitude did source bail out?

900 feet.
Were any of the crew injured or killed before the plane crashed?
No

What members of the crew bailed out? Did their parachutes open?

Did the plane explode on striking the ground?

Yes.

Did source see any other members of the crew dead or alive after reaching the ground?

Yes, one alive.

Did he receive any information from others as to whether any other members of the crew were dead or alive? If so, give details furnished by his informant and whether the other crew members were identified by name or otherwise.

Yes, was told by underground of 6 prisoners. Radio operator and I were together. Did source examine the wreckage of the plane? If so, what was its condition? No

If the plane crashed in water how far was the plane from land and by what means was source resoured and what life rafts, wreckage, etc., remained on the surface that would have assisted other personnel to keep affort.

Crashed on land.

What is source's opinion as to the fate of the other crew members and his reason for his opinion?

Six of the crew are prisoners; informed by underground. Two were with the underground. The pilot was missing but believed safe.

M	ZED.	EAT	AIF	RORAFT
2450	STREET	7.		

28 July 44, time: 1215

district 10.

KU 2573

MANTE OF CRASE --- "

Charlroi

THE OF MERCRIPT

Portress

Deporture depice

Air District Belginn North France

 NGE		RANE	Serial Number	CAPTID TOOMEED TEAD	Macs of Int	BRO SET
 HOOLLEY	Robert A.	2nd/Ert.	0-757762	captured	Dulsg Luft	
WILLIAMS	Claude Armin		ე_5 9 9497	•	Q *	
DWYER	wilbur Stevens	lst/Lt.	0-808596		• •	
EARRINGTON	Robert Elward	s/sgt.	12096518	•		•
BOKESMA	Ted	T/Sgt.	36724 862		* *	
Hotz	Jos a or	Lt.	0-703292	behauor	Hospital, 2	3.mg 44 blag.
HOVEY	Richard	Sgt.	37665898	9	dto.	



3 2373

On 745 41

: Officer's Identification Gard Br., 2053630

ED 2573

20 July 1964

Report in contered encey mirerest equipment ed espiced regions of many air feroes.

> Distributed to: Computing Station West Character 1 x

Time of exacts Process of creek type of species

Greeks. first of continue Meerch for orest

Sent with cartains Sir-orefts

Continued sevineties and F.T. Deter

CARTAINS STEPS

26 July 1964, Time 12th (shet down on may back) Smalleress-Sentet (village), 12 m III Merel Positive 5 17 5

burned out in around Treedings 25-90 \$

propunatly hole of coaft
shorted to hephylories & Air Flora Florestee at Charletel, 21m 1460

he his Pield Configuration, & (v) 215/H, his Pield Comment Committee

I reognaphie map and 2 serigation and 7.1. Just

s'arc as fallows: Mr. 1978; Makeri, M. 1955/1988; Mondad, St. 60 / Ads., tempolarization to Suspending Station Start Lat. Marriages, Maker, 1969/1987 1 (5-27 LAS.) 201 Marriages, Name Wildelford 1 (5-27 LAS.)

OF STATE OF THE PARTY OF The St. Mile, July 1994,

Et. Billes - 5712 T 1-1-10 In It. WOLLE, Before MENTS: 13-43-4 Total Total

time and place of inches to be a large 19th. Life.

Toubside Tribe

Treebyen Publings Low S & Bonding poor // & 3 Minus Low S, Mallion 50 S.
Type of Malary Stationary Supplies of Salary Salary Section Salary Consultation 1.) /-/ A QUE

S arecine

3.} THEFILE E **9** 5

A (mi to identity) are later **30.5**

Type: Bailte Stanfard potal Propillars 3 blacks . finalite. Propolier heliane r - 184 e.7 . 2 - 12V

Mode on this part has a depth tee! 126 mm

(abots) on Jose A 41 (page 1)ered out the real and the second

mr.

A william 2/2/type 1-1829-1 - Ion at the colored law and the colored law at the colored l

2 x 643945

The second second 2 x 64946

here time spread to dote in a balt

bells of enverting winteres. It is smiller all the soun

of beth wight open prints not to identify,

T. L. Speignerst

The formation and Small

 les la Viller S. Depur

Mar Lit. Clause A. Villiant

And Lt. Robert A. Wolley

Int. 14. January E. Beite.

Title But British

Title, begins billy

Office Spice To Just

Marie Continues

Will black & Now

See July P. Royer (better) ACR Street Street Months, Schools

Section State State (Section)

State State State State (Section)

STATE OF THE PARTY OF THE PARTY

	+11		
		3	

